

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 12 ALDEN ST
Building ID 124
Parcel No. (PID) 12-1-029-0
Mapbase # 12-1-029
Building Area 748.733
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850-1880
Source NR Nomination
Style/Form Greek Revival, Vernacular
Architect/Builder
Exterior Material wood shingle
Foundation obscured
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Addition

Condition Good
Moved no yes **Date**
Acreage 0.117
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

12 Alden Street is a 2-story, 5-bay residence with offset entry. The southern 3-bay section of the side gable roof is taller than the remainder of the main roof to accommodate an additional bay in depth. Brick ridge chimney is located on this taller section, and a second brick chimney is located on the rear slope of the 1-pile (north) section. Partial cornice returns and frieze below eaves. The main entry door is a replacement diamond patterned diamond pane door with shallow flat hood. Windows are 2/2 wood DHS with storms and wood surrounds. A 1-story addition is located at the northwest corner of the building.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*