

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

<b>Town</b>	Provincetown
<b>Place</b> <i>(neighborhood or village)</i>	
<b>Address</b>	5 TREMONT ST
<b>Building ID</b>	1450
<b>Parcel No. (PID)</b>	06-4-080-0
<b>Mapbase #</b>	06-4-080
<b>Building Area</b>	1747.478
<b>Historic Name</b>	
<b>Present Use</b>	Commercial - Lodging
<b>Original Use</b>	Residential
<b>Date of Construction</b>	1905
<b>Source</b>	Tax Assessment
<b>Style/Form</b>	Colonial Revival
<b>Architect/Builder</b>	
<b>Exterior Material</b>	Shingle
<b>Foundation</b>	brick
<b>Wall/Trim</b>	wood
<b>Roof</b>	cross hipped
<b>Outbuildings/Secondary Structures</b>	

### Major Alterations *(with dates)*

### Condition

**Moved**  no  yes **Date**

**Acreage** 0.115

### Setting

**Recorded by** Vanessa Zeoli  
**Organization** Kise Straw & Kolodner  
**Date** *(month/year)* April 2004

**Form Status**  new  update

Assessor's Number USGS Quad Area(s) Form Number

*Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.*

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

2 1/2-story, 5-bay; asphalt roof shingles; hipped dormer; rear shed dormer; rear interior brick chimney; slight wall flare between 1st and 2nd floors; overhanging eave; bands of diamond shaped wood shingles; main entrance contains multi-pane wood door with modern storm accessing full facade front porch with flat roof, square wood balustrade, decorative brackets, exposed roof rafters, balustrade around roof, lattice work at bottom and reached by centered wood steps; 2/1 wood DHS on front facade with inoperable shutters, 6/6 wood DHS in dormer, 2/1 wood DHS on east side in shed dormer, windows on 1st floor at rear of east side has Greek Revival window surrounds; 2/1 wood DHS, 1/1 vinyl DHS on west side; steps and deck on 2nd floor rear entrance on east side; open 1st floor deck extends along rear of west side.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

Currently "Shire Max Inn"

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*