## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown

Place (neighborhood or village)

Address 12 FRANKLIN ST

Building ID 143

 Parcel No. (PID)
 06-4-084-0

 Mapbase #
 06-4-084

 Building Area
 1550.918

**Historic Name** 

Present Use Residential - Multi-unit

Original Use Residential

**Date of Construction 1830** 

Source NR Nomination

Style/Form Astylistic

Architect/Builder

**Exterior Material** wood shingle

Foundation brick
Wall/Trim wood
Roof Irregular

**Outbuildings/Secondary Structures** 

Major Alterations (with dates)

alterations (1850-1860); Additions

**Condition** Good

Moved ✓ no □ yes Date

Acreage 0.147

Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner

Date (month/year) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICA	ON				
FORM B - BUILDING					
ARCHITECTURAL DESCRIPTION	see continuation sheet				
Describe architectural feaures. Evaluate the characteristics of		r buildings in the comm	unity		
This is a 1 1/2-story building on a raised brick foundation largest central block, which has a side gable roof with ce west have greatly expanded this building. A concrete ch main entry door on the 1st story is currently located at the level entries are currently located on the southern facade proportions. 6-light windows are located in the basement facade.	n, such that a full basement lentral brick chimney at the rich imney is located on the wes le north end of the east façace of the main, south, and we	evel is provided. The dge. Additions to the tern addition, and a bde. Wood stairs lead stern blocks. Window	main block appears north (with current m rick chimney on the to this pane and par s are generally 6/6 I	nain entry southern nel door. DHS woo	y), south and section. The Basement d, in varying
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations we within the community.		ude uses of the building	, and the role(s) the o	wners/occ	upants played
BIBLIOGRAPHY and/or REFERENCES	□ see continuation sheet				
BIBLIOGRAPHI AIIWOI REPERENCES	See continuation sheet				
Recommended for listing in the National Register Criteria Statement form.	of Historic Places. If checke	ed, you must attach a	completed National	Register	