

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown  
**Place** (neighborhood or village)  
**Address** 10 CONANT ST  
**Building ID** 36  
**Parcel No. (PID)** 06-4-174-0  
**Mapbase #** 06-4-174  
**Building Area** 845.017  
**Historic Name**  
**Present Use** Residential - Multi-unit  
**Original Use** Residential  
**Date of Construction** 1870  
**Source** Tax assessment  
**Style/Form** Astylistic  
**Architect/Builder**  
**Exterior Material** wood shingle  
**Foundation** brick  
**Wall/Trim** wood  
**Roof** Side gable  
**Outbuildings/Secondary Structures**  
 1-story secondary building

### Major Alterations (with dates)

Main entry removed (20th cent.)

**Condition** Good  
**Moved**  no  yes **Date**  
**Acreage** 0.092  
**Setting**

**Recorded by** Johnette Davies  
**Organization** Kise Straw & Kolodner  
**Date** (month/year) April 2004  
**Form Status**  new  update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

This former 2-story, 3-bay sidehall cottage has had fenestration altered so that entries are now on the south side gable façade. Roof has partial cornice return and frieze below eaves; brick chimney at roof ridge. A large shed wall dormer fills out the 2nd story on the south façade; a similar dormer is on the north roof slope. The entries are now on the south façade, and each contains a multi-pane and panel entry door with screens, accessed by a brick stoop. A shed roof overhangs each door. Windows are grouped and single 2/1 DHS. Rear facade has decks at each level, with spiral stair accessing a roof deck on the south roof slope. A 1-story front-gable roof addition is located at the northwest corner of the building. This has paired single-light casements and a separate entry door. A wooden stair b/w the main building and addition accesses a 2nd story deck and entry at the rear of the main building.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*