

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown  
**Place** (neighborhood or village)  
**Address** 5 CONANT ST  
**Building ID** 1416  
**Parcel No. (PID)** 06-4-176-0  
**Mapbase #** 06-4-176  
**Building Area** 170.457  
**Historic Name**  
**Present Use** Residential  
**Original Use** Residential  
**Date of Construction** 1950<  
**Source** NR Nomination  
**Style/Form** Astylistic  
**Architect/Builder**  
**Exterior Material** vinyl  
**Foundation** obscured  
**Wall/Trim** vinyl  
**Roof** side gable  
**Outbuildings/Secondary Structures**

### Major Alterations (with dates)

Cladding altered.

**Condition** Good  
**Moved**  no  yes **Date**  
**Acreage** 0.085  
**Setting**

**Recorded by** Vanessa Zeoli  
**Organization** Kise Straw & Kolodner  
**Date (month/year)** April 2004  
**Form Status**  new  update

Assessor's Number    USGS Quad    Area(s)    Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

This is a 1-story, 2-bay cottage. The side gable roof is clad in asphalt shingles. Door details were not visible during survey, however according to tax assessor's photograph, the main entry door is a pane and panel door flanked by shutters. Fenestration includes 6/6 wood DHS on south gable end with inoperable shutters; 6/6 vinyl DHS in north gable end at attic/loft.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*