

# MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown  
**Place** (neighborhood or village)  
**Address** 11 ATLANTIC AVE  
**Building ID** 82  
**Parcel No. (PID)** 07-2-086-0  
**Mapbase #** 07-2-086  
**Building Area** 822.146  
**Historic Name**  
**Present Use** Residential  
**Original Use** Residential  
**Date of Construction** 1900  
**Source** Tax assessment  
**Style/Form**  
**Architect/Builder**  
**Exterior Material** wood shingle  
**Foundation** brick  
**Wall/Trim** wood  
**Roof** front gable  
**Outbuildings/Secondary Structures**

### Major Alterations (with dates)

alterations, c. 1960

**Condition** Good  
**Moved**  no  yes **Date**  
**Acreage** 0.068  
**Setting**

**Recorded by** Vanessa Zeoli  
**Organization** Kise Straw & Kolodner  
**Date** (month/year) April 2004  
**Form Status**  new  update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

11 Atlantic Avenue is a 2-story, 3-bay center entry dwelling. The front-gable roof is clad in asphalt shingles; partial cornice returns; interior brick chimneys at south slope. A piece of trim across the gable end creates a full gable effect. The second story flares out slightly over the first story, and the flare is accented with wood trim. The primary entrance consists of a pane and paneled aluminum door with storm, accessed by wood steps and handrail. Fenestration includes 6/1 wood DHS with inoperable shutters. A vestibule is located on south facade contains a secondary entrance. The gable roof has a full return. The west-facing entry consists of a modern pane and panel aluminum door with storm. A wood open deck leads from the street to the entrance vestibule at the side.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*