

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 56 BRADFORD ST
Building ID 1489
Parcel No. (PID) 07-2-117-0
Mapbase # 07-2-117
Building Area 1303.634
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1951
Source Tax assessment
Style/Form Colonial Revival
Architect/Builder
Exterior Material clapboard
Foundation concrete block
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures
 1 former garage.

Major Alterations (with dates)

Condition Good
Moved no yes **Date**
Acreage 0.101
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) 3/5/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

56 Bradford Street is a 1-story, 3-bay gable front dwelling with a rear ell. The central entrance contains a panel door surrounded by pilasters and a denticulated entablature. A fanlight with snap-in muntins is located above the door surround. There is a small brick stoop at the front entry, with metal railings. Windows are 6/1 replacement DHS, and they are flanked by inoperable shutters. A secondary entry is located at the end of the side (northeast) elevation. There are skylights in the roof slope. The west façade contains 6/1 DHS with operable shutters. The east façade contains wood 6/1 DHS and secondary entry.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*