

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 77 BRADFORD ST
Building ID 1778
Parcel No. (PID) 07-4-004-0
Mapbase # 07-4-004
Building Area 1086.674
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850
Source Henry F. Walling Map, 1858
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard
Foundation obscured
Wall/Trim wood
Roof Side gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

porches added, c. 1980s; canted bay window

Condition Good
Moved no yes **Date**
Acreage 0.117
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) 3/8/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

77 Bradford Street is a 2-story, 3-bay, Greek Revival-style sidehall dwelling; the roof is side gable, it has a full return and entablature, a brick chimney is located at the roof ridge, and shed dormers, with slight returns, have been added to the front and rear roof slopes. ; the exterior is clad in clapboard, the facades are framed by pilasters, coved cornice at the gable ends, and the foundation is obscured; the fenestration includes 6/6 vinyl DHS replacements with wood trim and entablatures, a canted bay window has been added to the gable end facing north; the entablature of windows on the 1st story meet the frieze board; An enclosed porch has been added to the rear, and a deck is located on top of the porch roof.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

As per Josephine Del Deo (1977): "This house was originally built as used as a residence and has remained in stately residential use for 125 years. It is not untypical of many similar residences in the community which gives testimony to a continuous and unchanging community base as well as little altered architectural scale."

Owned by Mrs. G. De Wolf in 1858, A. Snow in 1880.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Walling, Henry F. "Map of Provincetown", 1858.
Village of Provincetown Map, 1880.
Resident Directory of Provincetown, 1885.

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*