

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

| Roll | Negative(s) |
|------|-------------|
| | |



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate north.

Town Provincetown
Place (neighborhood or village)
Address 89 BRADFORD ST
Building ID 1865
Parcel No. (PID) 11-3-058-0
Mapbase # 11-3-058
Building Area 674.935
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1847
Source Tax assessment
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard
Foundation concrete block
Wall/Trim
Roof Front gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Plaque: State of Massachusetts Historical Building, built in 1847. Rebuilt in 1995 by AAA Builders.

Condition Good
Moved no yes **Date**
Acreage 0.05
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) 3/8/2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This building is a 1 1/2-story, 2-bay cottage with a small side ell. The primary door is reached by wood steps with a small landing. The pane and panel door is surrounded by pilasters and a large entablature. Windows are 6/6 DHS with wood trim. The building is clad in clapboard on the primary façade, and wood shingles on the secondary facades. The side ell has a gabled dormer with 1 1/1 DHS window on the front roof slope. The front-gable roof has partial cornice returns. There are 2 skylights present on the southwestern roof slope. This side façade also has 6/6 DHS windows and a 3-light awning window.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*