

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 22 ALDEN ST
Building ID 610
Parcel No. (PID) 12-1-033-0
Mapbase # 12-1-033
Building Area 1074.873
Historic Name
Present Use Residential - Multi-unit
Original Use Residential
Date of Construction 1850-1870
Source NR Nomination
Style/Form Greek Revival
Architect/Builder
Exterior Material wood shingle
Foundation stuccoed
Wall/Trim wood
Roof Front gable
Outbuildings/Secondary Structures

Major Alterations (with dates)

Multi-unit conversion; 2-story addition; window sash & siding (1988)

Condition Fair
Moved no yes **Date**
Acreage 0.138
Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

22 Alden Street is a 2-story, 3-bay sidehall dwelling with a 2-story rear addition and wood shingle cladding. The front-gable roof has asphalt shingle cladding, partial returns, shed dormer on north slope, and gable dormer on south slope. Minimal corner pilasters; frieze below eaves. The main entry contains an oval pane and panel door with storm; surround with entablature and pilasters. Fenestration includes replacement wood 1/1 DHS with storms. A secondary entry is located near the rear of the south facade. The 2-story rear addition contains 1/1 and 2/1 DHS windows. Exterior steps to a second-story entry at the rear of the addition.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*