

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 15 ALDEN ST
Building ID 264
Parcel No. (PID) 12-1-041-0
Mapbase # 12-1-041
Building Area 1117.559
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1870-1890
Source NR Nomination
Style/Form Italianate
Architect/Builder
Exterior Material shingle
Foundation brick
Wall/Trim wood
Roof front gable

Outbuildings/Secondary Structures

side gable shed with board and batten wood siding.

Major Alterations (with dates)

addition

Condition Good
Moved no yes **Date**
Acreage 0.081
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update
Assessor's Number **USGS Quad** **Area(s)** **Form Number**

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

15 Alden Street is a 1 1/2-story, 3-bay sidehall dwelling clad in wood shingles. The front-gable roof is clad in asphalt shingles; partial returns. Gable dormer on south roof slope; gable wall dormer on north; exposed rafters under 1-story section on east; interior concrete block chimney at peak. Corner boards and frieze frame facades. The former main entry, facing the street, contains a pane and panel door with wood surround, flat hood with decorative end brackets, suspended with no step access. The primary entrance is now on south side, and it includes a pane and panel aluminum wood door with modern storm, accessed by brick steps. Fenestration includes 2/2 vinyl DHS. A 1-story rear section (east) has an entry door, also facing south near the rear. The door and steps are the same as the current primary entry on this façade, described above. Corner boards and frieze are also present on this 1-story section..

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*