

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

--	--	--	--

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll	Negative(s)



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Town Provincetown
Place (neighborhood or village)
Address 5 ALDEN ST
Building ID 1395
Parcel No. (PID) 12-1-045-0
Mapbase # 12-1-045
Building Area 806.412
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1830-1850
Source NR Nomination
Style/Form Astylistic
Architect/Builder
Exterior Material vinyl
Foundation brick
Wall/Trim vinyl
Roof cross gable
Outbuildings/Secondary Structures
 1-story shed/workshop

Major Alterations (with dates)

1-story rear ell; siding (1980s)

Condition Good
Moved no yes **Date**
Acreage 0.056
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (month/year) April 2004
Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

--	--	--	--

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

This is a 1 1/2-story, 5-bay building with asphalt shingle-clad side gable roof. The roof has partial cornice returns; shed dormer on front (west) roof slope with 6/6 DHS wood windows; rear (east) shed dormer with 1/1 DHS vinyl; stuccoed (brick) interior chimney at peak. Main entry is a pane and panel wood door with modern aluminum storm. Fenestration outside of dormers is generally 2/2 wood DHS. A 1-story gable roof ell addition with concrete block foundation is located at the rear. An exterior stair leads to a 2nd floor entrance at the rear.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*