

MASSACHUSETTS HISTORICAL COMMISSION FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

MASSACHUSETTS HISTORICAL COMMISSION
MASSACHUSETTS ARCHIVES BUILDING
220 MORRISSEY BLVD
BOSTON, MA 02125

Town Provincetown
Place (*neighborhood or village*)
Address 13 WAREHAM ST
Building ID 186
Parcel No. (PID) 12-1-063-0
Mapbase # 12-1-063
Building Area 770.627
Historic Name
Present Use Residential
Original Use Residential
Date of Construction 1850
Source Tax assessment
Style/Form Greek Revival
Architect/Builder
Exterior Material clapboard-front, shingle-side
Foundation concrete block
Wall/Trim wood
Roof side gable-asphalt
Outbuildings/Secondary Structures

Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

| Roll | Negative(s) |
|------|-------------|
| | |



Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

Major Alterations *(with dates)*

Condition Good
Moved no yes **Date**
Acreage 0.065
Setting

Recorded by Vanessa Zeoli
Organization Kise Straw & Kolodner
Date (*month/year*) April 2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSION

FORM B - BUILDING

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

ARCHITECTURAL DESCRIPTION

see continuation sheet

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.

13 Wareham Street is a 1-story, 3-bay dwelling; side-gable roof is sheathed in asphalt shingles; interior brick chimney on front roof slope near ridge; exterior is clad in clapboard siding with wood shingles on the secondary facades; wood corner boards and trim; center entry has wood surround with flanking fluted pilasters and denticulate entablature; entry is accessed by wood deck from south side; fenestration includes 1/1 vinyl DHS, paired 6/6 DHS wood in gable, and canted oriel window on left of front facade (west) supported by brackets.

HISTORICAL NARRATIVE

see continuation sheet

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*