## MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BLVD BOSTON, MA 02125

## **Photograph**

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll Negative(s)



## **Sketch Map**

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

**Town** Provincetown

Place (neighborhood or village)

Address 160 BRADFORD ST

Building ID 344

Parcel No. (PID) 12-3-058-0

Mapbase # 12-3-058

Building Area 1697.368

**Historic Name** 

Present Use Commercial - Lodging

Original Use Residential

**Date of Construction 1860** 

Source Plaque on building

Style/Form Stick

Architect/Builder

**Exterior Material** abestos shingle

Foundation brick
Wall/Trim wood
Roof Gambrel

**Outbuildings/Secondary Structures** 

Major Alterations (with dates)

**Condition** Good

Moved ✓ no ☐ yes Date

Acreage 0.135

Setting

Recorded by Johnette Davies
Organization Kise Straw & Kolodner

Date (month/year) 1/13/2004

Form Status new update

Assessor's Number USGS Quad Area(s) Form Number

Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.

MASSACHUSETTS HISTORICAL COMMISSI		ON			
FORM B - BUILDING					
		1			
ARCHITECTURAL DESCRIPTION	see continuation sheet				
Describe architectural feaures. Evaluate the characteristics Currently "Seasons: An Inn for All"; 160 Bradford Street	t is a 2-story, 2-bay building.	The gambrel roof has	s flared eaves and a		
gable end. This truss and a squared bay window on the Gothic Revival. The squared bay window faces Pearl S shallow, shed-roofed wall dormers break the roof cornic open porch with chamfered posts is located on the east mansard roof section with a separate entry is located to and rosettes where the wall dormer break the gable roof.	Street. The remainder of the ce on the west façade. Brack tern façade. A brick interior content of the rear. This also has 2/2 less the rear.	windows are single or ets are located hare a himney is located on	paired 2/2 DHS with and at the bay windouthe roof slope, near	h inopera ow eaves. the ridge	ble shutters. 2 . A 1-story . A 1 story
HISTORICAL NARRATIVE	see continuation sheet				
Discuss the history of the building. Explain its associations within the community.	with local (or state) history. Incl	lude uses of the building	g, and the role(s) the o	wners/occ	upants played
BIBLIOGRAPHY and/or REFERENCES	see continuation sheet				
<ul> <li>Recommended for listing in the National Registe</li> <li>Criteria Statement form.</li> </ul>	er of Historic Places. <i>If checke</i>	ed, you must attach a	completed National	Register	