

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING



MASSACHUSETTS HISTORICAL COMMISSION  
MASSACHUSETTS ARCHIVES BUILDING  
220 MORRISSEY BLVD  
BOSTON, MA 02125

### Photograph

(3"x3" or 3-1/2"x5" black and white only) Label photo on back with town and property address. Record film roll and negative numbers here on the form. Staple photo to left side of form over this space. Attach additional photos to continuation sheets.

Roll    Negative(s)

--	--



**Town** Provincetown

**Place** (neighborhood or village)

**Address** 224 BRADFORD ST

**Building ID** 633

**Parcel No. (PID)** 15-1-045-0

**Mapbase #** 15-1-045

**Building Area** 962.193

**Historic Name**

**Present Use** Residential

**Original Use** Residential

**Date of Construction** 1920-1930

**Source** NR Nomination

**Style/Form**

**Architect/Builder**

**Exterior Material** wood shingle

**Foundation** concrete block

**Wall/Trim** wood

**Roof** Side gable

**Outbuildings/Secondary Structures**

### Sketch Map

Draw a map showing the building's location in relation to the nearest cross streets and/or major natural features. Show all buildings between inventoried building and nearest intersection or natural feature. Label streets including route numbers, if any. Circle and number the inventoried building. Indicate

### Major Alterations (with dates)

**Recorded by** Johnette Davies  
**Organization** Kise Straw & Kolodner  
**Date (month/year)** 2/17/2004  
**Form Status**  new  update

Assessor's Number    USGS Quad    Area(s)    Form Number

**Condition** Good  
**Moved**  no  yes    **Date**  
**Acreage** 0.101  
**Setting**

*Follow Massachusetts Historical Commission Survey Manual instructions for completing this form.*

# MASSACHUSETTS HISTORICAL COMMISSION

## FORM B - BUILDING

--	--	--	--

### ARCHITECTURAL DESCRIPTION

see continuation sheet

*Describe architectural features. Evaluate the characteristics of this building in terms of other buildings in the community.*

224 Bradford Street is a 1 1/2-story, 4-bay bungalow; the roof is side gable, a gable-roofed dormer is centrally located on the front roof slope, an exterior end brick chimney interrupts the west slope and a concrete block exterior chimney is located in the rear portion of the west façade; the exterior is clad in wood shingles and the foundation is concrete block; the fenestration includes 6/1 wood DHS, 2/1 DHS replacements with snap-in muntins and aluminum storms, single-light basement windows, and 4-light window in the dormer; the primary entrance includes and enclosed, incised porch accessed by a wooden storm door; a deck is present on the rear of the building.

### HISTORICAL NARRATIVE

see continuation sheet

*Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.*

### BIBLIOGRAPHY and/or REFERENCES

see continuation sheet

- Recommended for listing in the National Register of Historic Places. *If checked, you must attach a completed National Register Criteria Statement form.*